



# **FRUITLAND MAGNESIUM FIRE INCIDENT**

**INCIDENT # CA-LAC-170501**



## **FIRE IMPACT INSPECTION REPORT JUNE 23, 2016**

**Prepared by LACoFD  
Health Hazardous Materials Division  
Damage Inspection Team**

# **FRUITLAND MAGNESIUM FIRE INCIDENT**

**INCIDENT # CA-LAC-170501**

## **TABLE OF CONTENTS**

- 1) FIRE IMPACT INSPECTION NARRATIVE**
- 2) FIRE IMPACT INSPECTION PROPERTY LIST**
- 3) FIRE IMPACT INSPECTION REPORTS AND PHOTOS**
- 4) FRUITLAND MAGNESIUM FIRE MAP**

# FRUITLAND MAGNESIUM FIRE INCIDENT

## INCIDENT # CA-LAC-170501

### FIRE IMPACT INSPECTION NARRATIVE

The Fruitland Magnesium Fire Incident started on June 14, 2016 at 0231 hours. Vernon Fire and the County of Los Angeles Fire Department responded to the single story commercial structure fire. The fire originated at 3570 Fruitland Avenue in the City of Maywood in the County of Los Angeles, California. The building was occupied by a processor and broker of recyclable metals with a portion subleased to a metal extracting reclamation business. The origin and cause of the fire is under investigation by the County of Los Angeles Sheriff's Department.

Approximately 300 individuals were evacuated from nearby homes and businesses due to dangerous conditions created by the intense fire and air quality issues. Areas evacuated included residences immediately south of the facility (mandated) and a voluntary evacuation Ex. 6 - Personal Privacy feet along with restricted access to the businesses near the facility on Fruitland Avenue. Additionally, businesses north of Fruitland Avenue in the City of Vernon were also notified to remain out of their business locations. Businesses impacted on Fruitland Avenue in the City of Maywood included:

- Keeney Truck Lines at 3500 Fruitland Avenue
- Pacific Machinery Moving 3544 Fruitland Avenue
- Gemini Plastic 3574 Fruitland Avenue

Street closures occurred at Fruitland Avenue from Downey Avenue to Corona Avenue and Loma Vista Avenue from District Boulevard to East 52nd Street and 52nd Street from Loma Vista Avenue to Maywood Avenue.

The fire was extinguished on June 16, 2016. The incident was relinquished to the Unified Command consisting of the County of Los Angeles (LACo) Fire Department Health Hazardous Materials Division, LACo Public Health, and the United States Environmental Protection Agency (US EPA). Other cooperating and assisting agencies included, the Department of Toxic Substances Control, the LACo Sheriff's Department, South Coast Air Quality Management District, California Department of Fish and Wildlife, the LACo Building and Safety, the LACo Department of Public Works, the LACo Department of Social Services, the LACo Internal Services Department, Vernon Fire Department, Vernon Health Department, the City of Maywood, the California Office of Emergency Management, United States Coast Guard, and the American Red Cross.

Under the Unified Command, US EPA contractors are conducting sampling activities of homes on the Ex. 6 - Personal Privacy lot to evaluate contaminants from the fire. On an order from the LACo Health Officer, evacuations remained in effect for houses on the Ex. 6 - Personal Privacy. This report is a listing of the residential properties impacted by the fire and also includes the business where the fire originated.

FIRE IMPACT INSPECTION PROPERTY LIST FRUITLAND MAGNESIUM FIRE CA-LAC-170501										
R#	ADDRESS	STREET	CITY	TYPE OF STRUCTURE	STRUCTURE		ASH OBSERVED		VEHICLES	APN
					DESTROYED	DAMAGED	YES*	NO	DAMAGED	
1	3570	Fruitland Ave.	Maywood	Commercial	2		X			Ex. 6 - Personal Privacy
2	Ex. 6 - Personal Privacy		Maywood	MFD			X			
3			Maywood	SFD				X		
4			Maywood	MFD			X			
5			Maywood	MFD		1	X			
6			Maywood	MFD		1	X			
7			Maywood	SFD		1	X		1	
8			Maywood	SFD			X			
9			Maywood	SFD		1	X			
10			Maywood	SFD			X			
11			Maywood	SFD			X			
12			Maywood	SFD		1	X		1	
13			Maywood	SFD		1	X			
14			Maywood	SFD		1	X			
15			Maywood	SFD			X			
16			Maywood	SFD			X			
17			Maywood	SFD			X			
18			Maywood	SFD			X			
19			Maywood	SFD			X			
				TOTAL	2	7	18	1	2	

\* Note: Photographs taken only at properties with sufficient background contrast to illustrate the presence of ash.

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 1

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: 3570 Fruitland Avenue

APN Number: 6311-017-042

Type of Structure: ☐ Single Family ☐ Outbuilding/Other ☐ Detached Garage  
☐ Multi Family ☐ Mobile Home ☒ Commercial ☐ Vehicle

Extent of Damage: ☐ Minor ☐ Moderate ☐ Major ☒ Destroyed

Exterior Construction Material: ☐ Stucco ☐ Masonry ☒ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☐ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☒ Unknown

Window Type: ☐ Single Pane ☐ Double Pane ☒ Unknown

Eaves: ☐ Exposed ☐ Enclosed ☒ Unknown

Vents: ☐ Screened ☐ Unscreened ☒ Unknown

Deck: ☐ Attached ☐ Detached ☒ Unknown

Comments: Two buildings and a large overhead structure destroyed.

## REPORT #1 – 3570 Fruitland Avenue

**PHOTO #1 – Front view of 3570 Fruitland Avenue.**



**PHOTO #2 – Rear view of 3570 Fruitland Avenue.**



# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 2

## FIRE IMPACT INSPECTION FORM

Inc. #	CA-LAC-170501	Date of Inspection:	6-23-16	Incident Type:	Chemical Fire
Property Address:	<div>Ex. 6 - Personal Privacy</div>				
APN Number:					
Type of Structure:	<input type="checkbox"/> Single Family	<input type="checkbox"/> Outbuilding/Other	<input type="checkbox"/> Detached Garage		
	<input checked="" type="checkbox"/> Multi Family	<input type="checkbox"/> Mobile Home	<input type="checkbox"/> Commercial	<input type="checkbox"/> Vehicle	
Extent of Damage:	<input type="checkbox"/> Minor	<input type="checkbox"/> Moderate	<input type="checkbox"/> Major	<input type="checkbox"/> Destroyed NA	
Exterior Construction Material:	<input checked="" type="checkbox"/> Stucco	<input type="checkbox"/> Masonry	<input type="checkbox"/> Metal	<input type="checkbox"/> Wood siding	<input type="checkbox"/> Unknown
Roof Covering:	<input checked="" type="checkbox"/> Asphalt Shingle	<input type="checkbox"/> Composition	<input type="checkbox"/> Tile	<input type="checkbox"/> Metal	<input type="checkbox"/> Wood Shake <input type="checkbox"/> Unknown
Window Type:	<input checked="" type="checkbox"/> Single Pane	<input type="checkbox"/> Double Pane	<input type="checkbox"/> Unknown		
Eaves:	<input checked="" type="checkbox"/> Exposed	<input type="checkbox"/> Enclosed	<input type="checkbox"/> Unknown		
Vents:	<input checked="" type="checkbox"/> Screened	<input type="checkbox"/> Unscreened	<input type="checkbox"/> Unknown		
Deck:	<input type="checkbox"/> Attached	<input type="checkbox"/> Detached	<input type="checkbox"/> Unknown NA		

Comments: The parcel includes 

Ex. 6 - Personal Privacy

Ex. 6 - Personal Privacy

 Ash observed photograph taken 6/17/16.

PHOTO #1 – Side view of property.





PHOTO #2 – Ash deposit on asphalt in carport area.





# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 3

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-23-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy

APN Number: 6311-017-037

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☐ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☐ Minor ☐ Moderate ☐ Major ☐ Destroyed NA

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☒ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☐ Single Pane ☒ Double Pane ☐ Unknown

Eaves: ☒ Exposed ☐ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: No damage observed. No ash observed

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 4

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy

APN Number: 6311-017-036

Type of Structure: ☐ Single Family ☐ Outbuilding/Other ☐ Detached Garage  
☒ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☐ Minor ☐ Moderate ☐ Major ☐ Destroyed NA

Exterior Construction Material: ☐ Stucco ☒ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☒ Single Pane ☒ Double Pane ☐ Unknown

Eaves: ☐ Exposed ☒ Enclosed ☐ Unknown

Vents: ☐ Screened ☐ Unscreened ☐ Unknown NA

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: Front units facing the street have double pane windows; the remaining windows are single pane.

Ash deposits observed; No property damage.

PHOTO #1 – Front view of property.




PHOTO #2 – Ash deposit on the walkway.




PHOTO #3 – Ash deposit on the walkway.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 5

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy Street

APN Number:

Type of Structure:  Single Family  Outbuilding/Other  Detached Garage

X Multi Family  Mobile Home  Commercial  Vehicle

Extent of Damage: X Minor  Moderate  Major  Destroyed

Exterior Construction Material: X Stucco  Masonry  Metal  Wood siding  Unknown

Roof Covering:  Asphalt Shingle  Composition  Tile  Metal  Wood Shake  Unknown

Window Type: X Single Pane  Double Pane  Unknown

Eaves: X Exposed  Enclosed  Unknown

Vents: X Screened  Unscreened  Unknown

Deck:  Attached  Detached  Unknown NA

Comments: Two windows damaged and boarded up (3' x 4').

Ash deposit observed.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

PHOTO #2 – Damaged window on east side of building.

**Ex. 6 - Personal Privacy**

PHOTO #3 – Ash deposits on west side of the building.

**Ex. 6 - Personal Privacy**

PHOTO #4 – Damaged window on west side of the building.

**Ex. 6 - Personal Privacy**



# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 6

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy et

APN Number: Ex. 6 - Personal Privacy

Type of Structure: ☐ Single Family ☐ Outbuilding/Other ☐ Detached Garage

☒ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☒ Minor ☐ Moderate ☐ Major ☐ Destroyed

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☒ Single Pane ☐ Double Pane ☐ Unknown

Eaves: ☐ Exposed ☒ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: Unit D west side window broken; (3'x4'). North side window boarded up (3'x3')

Ash deposit observed.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

PHOTO #2 – Ash deposits on south side of the building.

**Ex. 6 - Personal Privacy**

PHOTO #3 – Boarded window on the north side.

**Ex. 6 - Personal Privacy**

PHOTO #4 – Unit D west side window broken.

**Ex. 6 - Personal Privacy**

PHOTO #5 – Metal fragment on the concrete.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 7

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy  
APN Number: Ex. 6 - Personal Privacy

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☒ Minor ☐ Moderate ☐ Major ☐ Destroyed

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☒ Single Pane ☐ Double Pane ☐ Unknown

Eaves: ☐ Exposed ☒ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: Damaged windshield, black Honda Accord, plate number 5 Ex. 6 - Personal Privacy Broken rear window.

Damaged 3'x4' house window. Ash deposit observed.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

PHOTO #2 – Vehicle with rear windshield damage and ash deposits.

**Ex. 6 - Personal Privacy**

PHOTO #3 – Vehicle with windshield damage and ash deposits.

**Ex. 6 - Personal Privacy**

PHOTO #4 – Damaged window.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 8

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy

APN Number: \_\_\_\_\_

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☐ Minor ☐ Moderate ☐ Major ☐ Destroyed NA

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☐ Single Pane ☒ Double Pane ☐ Unknown

Eaves: ☒ Exposed ☐ Enclosed ☐ Unknown

Vents: ☐ Screened ☒ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: Ash deposit observed, difficult to photograph.

No damaged observed.



PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 9

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy

APN Number:

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☒ Minor ☐ Moderate ☐ Major ☐ Destroyed

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☐ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☒ Single Pane ☐ Double Pane ☐ Unknown

Eaves: ☒ Exposed ☐ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: Broken window (6'x3'); Rear block wall damaged.

Ash deposit observed, difficult to photograph.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

PHOTO #2 – Damaged rear wall.

**Ex. 6 - Personal Privacy**

PHOTO #3 – Damaged window.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 10

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: [Redacted]

APN Number: [Redacted]

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☐ Minor ☐ Moderate ☐ Major ☐ Destroyed NA

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☒ Single Pane ☐ Double Pane ☐ Unknown

Eaves: ☒ Exposed ☐ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown

Comments: Ash deposit observed, difficult to photograph.

No damaged observed.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 11

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy

APN Number: Ex. 6 - Personal Privacy

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☐ Minor ☐ Moderate ☐ Major ☐ Destroyed NA

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☒ Single Pane ☐ Double Pane ☐ Unknown

Eaves: ☒ Exposed ☐ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: Ash deposit observed, difficult to photograph.

No damage observed.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**



# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 12

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy

APN Number: Ex. 6 - Personal Privacy

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☐ Minor ☒ Moderate ☐ Major ☐ Destroyed

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☐ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☒ Single Pane ☐ Double Pane ☐ Unknown

Eaves: ☒ Exposed ☐ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: Back wall damaged; Black Toyota sedan burned, plate number Ex. 6 - Personal Privacy

Ash observed on car and ground.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

PHOTO #2 – Rear wall damaged.

**Ex. 6 - Personal Privacy**

PHOTO #3 – Damaged vehicle.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 13

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: [Redacted]

APN Number: [Redacted]

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☒ Minor ☐ Moderate ☐ Major ☐ Destroyed

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☒ Single Pane ☐ Double Pane ☐ Unknown

Eaves: ☒ Exposed ☐ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: Damaged window (2'x3').

Ash deposit observed.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

PHOTO #2 – Broken window.

**Ex. 6 - Personal Privacy**

PHOTO #3 – Ash observed on ground at detached garage.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 14

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy

APN Number: \_\_\_\_\_

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☒ Minor ☐ Moderate ☐ Major ☐ Destroyed

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☐ Single Pane ☒ Double Pane ☐ Unknown

Eaves: ☒ Exposed ☐ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: Damaged/burned ceiling joist and fire suppression damage to drywall at rear converted carport.

Ash deposit observed, difficult to photograph.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

PHOTO #2 – Ceiling drywall damage.

**Ex. 6 - Personal Privacy**



PHOTO #3 – Ceiling drywall and joist damage.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 15

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy

APN Number: Ex. 6 - Personal Privacy

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☐ Minor ☐ Moderate ☐ Major ☐ Destroyed NA

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☐ Single Pane ☒ Double Pane ☐ Unknown

Eaves: ☐ Exposed ☒ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: Ash deposit observed, difficult to photograph.

No damage observed.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 16

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy

APN Number: \_\_\_\_\_

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☐ Minor ☐ Moderate ☐ Major ☐ Destroyed NA

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☐ Single Pane ☒ Double Pane ☐ Unknown

Eaves: ☐ Exposed ☒ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: No damage observed.

Ash deposit observed, difficult to photograph.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 17

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy

APN Number: \_\_\_\_\_

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☐ Minor ☐ Moderate ☐ Major ☐ Destroyed NA

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☐ Single Pane ☒ Double Pane ☐ Unknown

Eaves: ☒ Exposed ☐ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: Ash deposit observed, difficult to photograph.

No damage observed.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 18

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy

APN Number: \_\_\_\_\_

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☐ Minor ☐ Moderate ☐ Major ☐ Destroyed NA

Exterior Construction Material: ☒ Stucco ☐ Masonry ☐ Metal ☐ Wood siding ☐ Unknown

Roof Covering: ☐ Asphalt Shingle ☐ Composition ☒ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☐ Single Pane ☒ Double Pane ☐ Unknown

Eaves: ☐ Exposed ☐ Enclosed ☐ Unknown NA

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: Ash deposit observed, difficult to photograph.

No damage observed.



PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

# FRUITLAND MAGNESIUM FIRE INCIDENT

Report # 19

## FIRE IMPACT INSPECTION FORM

Inc. # CA-LAC-170501 Date of Inspection: 6-21-16 Incident Type: Chemical Fire

Property Address: Ex. 6 - Personal Privacy

APN Number:

Type of Structure: ☒ Single Family ☐ Outbuilding/Other ☒ Detached Garage  
☐ Multi Family ☐ Mobile Home ☐ Commercial ☐ Vehicle

Extent of Damage: ☐ Minor ☐ Moderate ☐ Major ☐ Destroyed NA

Exterior Construction Material: ☐ Stucco ☐ Masonry ☐ Metal ☒ Wood siding ☐ Unknown

Roof Covering: ☒ Asphalt Shingle ☐ Composition ☐ Tile ☐ Metal ☐ Wood Shake ☐ Unknown

Window Type: ☒ Single Pane ☐ Double Pane ☐ Unknown

Eaves: ☒ Exposed ☐ Enclosed ☐ Unknown

Vents: ☒ Screened ☐ Unscreened ☐ Unknown

Deck: ☐ Attached ☐ Detached ☐ Unknown NA

Comments: No damage observed.

Ash deposit observed, difficult to photograph.

PHOTO #1 – Front view of property.

**Ex. 6 - Personal Privacy**

## FRUITLAND MAGNESIUM FIRE MAP

